

Appendix A: Photographs



Building Overview Looking Northeast



Property Overview Looking East toward Fitness Lane.



Existing end of driveway and fire hydrant at west end of structure.



Fitness Lane looking West to East.



Existing Shed located on West side of structure.



Existing shed positioned in parking lot.



Looking Northwest from Main Entrance.



Main Entrance with designated handicap parking and access ramp into facility.



Main Entrance looking North.



Main Entrance.



Lower End of Site on Northeast corner.



Existing driveway, Fitness Lane, along Front Entrance at North side.



Lower End of Site on East side.



Looking at East side



Lower End of Site looking toward Southeast corner



Backside of property facing South



Looking at Southeast corner of building



Looking Southwest at grade and retaining wall.



South side of property looking at slope and retaining wall.



South side of building, secured rear entrance.



Looking at south side of building showing gutters and downspout.



Looking at south side of building showing gutters and down spout.



South side of property, the retaining wall with weep holes in place, along the entire span.



Upper End of Facility looking North



Upper End of Site looking North



Private Physical Therapy Room